

USB-ITPAK

Measurement Data Collection Software

Although Measurement Data can be simply loaded directly into a Microsoft Excel® spreadsheet by connecting the instrument and input tool to a computer, using the optional USB-ITPAK software enables time-saving operations and procedures that significantly improve reliability and efficiency.

- ITPAK creates inspection routines that guide the operator through the required measurements and ensures data from each gage is input into the correct cell.
- This is a must-have software for individuals who use Microsoft Excel® spreadsheets for data collection.




■ Features of USB-ITPAK V2.1


- The measuring methods can be configured, such as sequential measurement, batch measurement, individual measurement and more.
- Data can be canceled by a single operation of the foot switch or function key.
- Input range can be specified per Digimatic Gage, reducing the chance of a misinput.
- Data input or cancellation can be triggered globally for multiple features and simultaneous measurement.
- The Microsoft Excel® spreadsheet can be automatically opened for data input.
- The cursor movement after data input can be set to enable automatic input.

USB-ITPAK is best used in high volume, multiple gage applications where the operator needs to ensure multiple data points are placed into the correct cells of their spreadsheet.

USB Foot switch Adapter



The USB Foot switch Adapter converts the Mitutoyo Foot switch into a USB device allowing it to be utilized by ITPAK to perform function such as: Data trigger, data cancel, and pass or fail for attribute collection. The cables are serialized so several can be used in one routine to perform dedicated functions.



Applications

Measurement Data Collection Software

Measurement values are input one by one according to a procedure previously defined by using one or more Digimatic Gages (via **IT-016U/USB-ITN** or **U-WAVE**).

(1) Measure outside diameter at X and Y of 5 workpieces with a micrometer.

(2) Measure length H of 5 workpieces.

(3) Inspect external view to check if there are any scratches or color shading and input "OK" or "NG".

The last data input may be canceled by pressing and holding the data switch

Character strings Input "OK" Input "NG" *No data request for U-WAVE.

Data request* Data cancel

When a measuring procedure is executed, a window (as below) is displayed. "Data request*", "Data cancel*", "Data skip*", "Aborting", "Complete" can be specified. * These operations can be allocated to the function key or foot switch (via USB-FSW).

Cell movement direction after inputting data (down and right)
Carriage return (Low, column)
Microsoft Excel® sheet previously specified

	A	B	C	D	E	F
1	Setting	1	2	3	4	5
2	Dimension X	10.025	10.033	9.964	10.031	10.046
3	Dimension Y	9.982	10.017	10.008	9.996	10.027
4	Dimension H	29.97	30.02	30.07	29.96	30.04
5	External Appearance	OK	OK	NG		

Input range of micrometer (B2 to F3)
Input range of caliper (B4 to F4)
Input range of visual judgment (B5 to F5)

Cell that will receive next input is highlighted in green

Simultaneous Measurement

Measurement values are input simultaneously from several Digimatic Gages (via **IT-016U/USB-ITN**, **U-WAVE**)

A special order U-WAVEPAK (Event drive) is required. (Refer to A-9.)

U-WAVE-T x 2 pcs.

U-WAVE-R

USB-ITN-C x 2

USB-FSW x 2 pcs. + Foot switch x 2 pcs.

Height A B C D

(Measurement examples)
Simultaneous measurement of the heights A to D on the workpiece below.

	A	B	C	D	E
1		Height A	Height B	Height C	Height D
2	1	5.02	8.03	9.96	6.03
3	2	4.98	8.02	10.01	5.99
4	3	4.97	8.04	10.07	5.96
5	4				
6	5				

First measurement (finished)
Second measurement (finished)
Third measurement (finished)
Fourth measurement (Wait for next input)

Individual Measurement

Several operators input measurement data asynchronously according to individually defined procedures (where to input, move direction, etc.) from each Digimatic Gage via **IT-016U/USB-ITN** or **U-WAVE**.

(Measurement example)
Two operators measure 6 workpieces (three each, both working at the same time)

Operator 1 (USB-ITN-C) measures Workpiece Nos. 1 to 3.
Operator 2 (U-WAVE-T) measures Workpiece Nos. 4 to 6.

The last data input may be canceled by pressing and holding the data switch

Since several individual operators perform measurement simultaneously, an operation key and a function key in the window below cannot be used at the same time. The only effective input device in this case is the foot switch (via USB-FSW).

	A	B	C	D	E	F	G
1	Setting	1	2	3	4	5	6
2	Dimension A	10.02	10.03	9.96	10.15	10.23	10.04
3	Dimension B	9.98	10.01	10.07	9.99	9.78	
4	Dimension C	10.15	10.14		9.96	10.27	

Cell that will receive next input
Cell that will receive next input